



Plastic Deformation: ^{Forging} UNIT 4 ^o Plastic deformation is deformation which is permanent and beyond the elastic range of the metal & often metals are worked by plastic deformation because of the beneficial effect that is imparted to the mechanical properties by it. The necessary deformation is achieved by application of large amount of mechanical force only or by heating the metal and then applying small force.

Deformation is due to displacement of the atoms by the process of slip or twinning. The details when plastic deformation occurs the metal appears to flow in the solid state along specific direction, which are dependant on the type of process & direction of applied force. The crystal or grains of the metal are elongated in the direction of metal flow. This flow of metal can be seen under microscope after polishing and suitable etching of the metal surface. These visible lines are called "fibre flow lines".

Since the grains are elongated in the direction of flow they would be able to offer more resistance to stresses acting across them. As a result the mechanically worked metals called wrought products would be able to achieve better mech. strength in sp. orientation than of the flow direction. These flow lines can be controlled by the manipulation of the applied force. Metal of course weak along the flow lines.

The wastage of material in metal working is either neg. negligible or very small, and the production rate is high with economy




(a) bar stock (b) forged steel

Forging :- Two types - ⁽²⁾ Forging is the operation where the metal is heated and then a force is applied to manipulate the metal in such a way that the required final shape is obtained. This is the oldest of the metal working processes known to mankind since copper age. Forging is generally hot working operation though cold forging is used sometimes.

Forging operation: - Two types of operations are used in forging in order to arrive at the final object configuration. They are

Drawing out: - This is the operation in which the ~~rod~~ metal gets elongated & a reduction in the cross-sectional area. For this purpose, the force is to be applied in a direction \perp to the length axis.

Upsetting is This applied to increase the cross-sectional area of the stock at the expense of its length. To ~~achieve~~ achieve the upsetting, force is applied in a direction \parallel to the length axis.



Forging has a manipulative ability, it is possible to closely control the grain flow in the specific directions such that the best mechanical properties can be obtained based on the specific application. grain flow directions are depicted.

It is possible of desirable grain flow. The grain pattern obtained without bending is shown in (a) whereas the one in (b) is obtained by bending after drawing out. As a result, the grain also bent along the hook and thus provides the necessary strength for lifting loads. Similarly the gear blank shown in (d) is obtained by upsetting the blank and then finishing

forging, whereas the one in (c) is obtained without upsetting the blank. The upsetting process provides the radial grain flow, which is essential for good strength in the gear tooth for severe applications.


- Forging types Four types of forging methods which are generally used. (1) Smith forging :- This is traditional traditional forging done openly or in open dies by village blacksmiths or modern shop floor by manual hammering or by power hammer.
- (2) Drop forging :- This is the opⁿ done in closed impression dies by means of drop hammers. Here the force for shaping

the component is applied in a series of hammers.

Press forging :- Similar to drop forging, press forging is also done in closed impression dies with the exception that the force is a continuous squeezing type applied by the hydraulic presses.

Machine presses: Unlike the drop or press forging where the material is drawn out, in machine forging, the material is only upset to get the desired shape.

Smith forging: The process involves heating the stock in the blacksmith's hearth and then beating it over the anvil. To get the desired shape, the operator has to manipulate the component in b/w the blows. Type of operations available are fullering, flattening, bending, upsetting and swaging.



In fullering operation bottom fuller is fitted on anvil and upon which heated work piece to be set and then top fuller is brought over the place and hammering (swage hammer)

is blowed the area of the work piece decreased at the centre of the fuller and repeating the operation by moving the up fuller and get the desired shape. After fullering the stock would have the fullering marks left which are then cleaned by means of flattening. To obtain specific shapes like round, square, hexagon

etc. open general purpose dies called swage blocks are used.

Smith forging involves a lot of skill on the part of the operator and also is more time consuming. But no dies are used, Smith forging is more beneficial in the making of small lots or in trial production, because heavy cost of closed impression dies cannot be justified in these cases.

Drop forging: In drop forging closed impression dies are used to obtain the desired shape of the component. This is obtained by the repeated blow of the hammer given to the material in the die cavity. The equipment used for delivering the blows are called drop hammer.

The die consists of two halves: Lower half is kept on anvil of the machine. While the upper die is fixed with the rammer of the hammer.

(5)

The heated stock is kept on the lower die and the ram delivers hammer blows ~~is~~ two to four on the metal, in quick succession. So that the metal spreads and completely fills the die cavity when the two die halves close - complete cavity is formed.



Shape of the impression is machined in the die cavity, because of which more complex shape can be obtained, in drop forging as compared to smith forging. However more complex, intricate shapes deep pockets, & re-entrant shapes etc cannot be obtained due to the limitation of the withdrawal of the finished product from the die. The products obtained are cranks, crank shaft, connecting rod, wrench, crane hook etc.

The final shape desired in deep forging is single pass. Depending on the shape of the component, and desired grain flow direction, the material should be manipulated in no. of passes.

→ Fulling impression: Here the reduction of the stock cross-section is obtained with no upsetting. The very first step is to reduce the stock size. The impression formed in the die is called fuller-ring impression.

→ Edging impression: Also called preform, this stage is required to gather the exact amount of material required at each cross-section of the finished component. This most important stage because it ensures preform, defect-free flow of metal, complete die fill and minimum flash loss.

Bending impression:



This is required for those component which has bent shape. For proper bending and the grain flow to obtained in the component, it is to be followed after edging impression.

Blocking impression:

in forging it is very difficult for sharp corners etc. to be allowed to have

this is also called semi finishing stage. in the material to flow to deep pockets. Hence before the actual shape is obtained, the mtl one or more blocking impression where it occurs the

very near to the final one. blocking impression are characterised by larger corner radii and billets but no flash. For complex shape more than one blocking impressions may be used. Finishing impression where the

Finishing impression :- This is the final impression where the actual shape required is completely filled in order to ensure the metal is completely fills the die cavity, a little extra metal is added to the stock. This extra metal will flow in the form of flash surrounds the forging in the parting plane.

Trimming :- In this stage, the extra flash present around the forging is trimmed to get the forging in the usable form.

Press forging :- Dies and process followed are same as drop forging. The metal is shaped not by means of a series of blows as in drop forging but by means of a single continuous squeezing action. This is obtained through hydraulic presses.

Continuous action of hydraulic presses, The material gets uniformly deformed throughout its entire depth. The force is transferred to stock where as in drop forging to machine frame. The impressions on stock is clear & clean as compared to drop forged mill. The draft angles are less than drop forging, but the press capacity is very high. So smaller components only are press forged in closed dies. But there is no limitation for open impression die.

The press capacity may vary from 5MN to 50MN for normal applications. and for heavy duty it may vary from 150MN to provide necessary alignment of the two dies, die posts are attached to the bottom die so that the top die would likely to slide only on the posts and thus register the correct alignment. No tong is required in press forging as in drop forging but the proper arrangement of fuller, bender, blocker finished to be true

Machine forging: — Also known as upset forging. Though both the drop and press forging is done by the machine but only upset forging is referred as machine forging. This was developed for making bolt heads in continuous fashion. but there are large no of diverse uses for this process. Because grains flow obtains, it is used for making gear blanks, shaft, axles, spindles etc.

Horizontal

The die set consists of a die and corresponding punches or a heading tool. The die consists of two parts, one called the stationary gripper die which is fixed to the machine frame, and the other movable gripper die, which moves along the die slide of the up setter. The stock is held between these two gripper dies by friction.

The up set forging starts with the stationary die to grip the stock. The two dies, when in closed position, form necessary die cavity. Then the heading tool advances against the stock and upset it to completely fill the die cavity. Having completed the upsetting, the heading tool moves back up to its back position. The movable gripper die releases the stock by sliding backwards.

Vertical: Similar to drop forging, it is not possible to get the final shape in a single pass in m/c forging too. Therefore the operation is carried out in a no. of steps. The die cavities required for the various operations are all arranged vertically on the gripper dies. The stock is then moved from one stage to the other in a proper sequence till the final forging is ready. A heading tool each, for every upsetting stage is arranged on the heading die slide of the upsetting machine.